
The following outline is taken from the Table of Contents of the Roadside Maintenance Guideline produced by Glacier National Park in July, 1993.

- I. Introduction
 - A. Policy
 - B. Objectives
 - C. Guideline Summary
- II. Road Corridor
 - A. Hazard Trees
 - B. Overgrown Vistas
 - C. Clogged Water Courses and Structures
 - D. Slumps
- III. Backslope
 - A. Lack of Transition to Undisturbed Area
 - B. Inadequate Sight Distance
 - C. Unstable Backslopes
 - D. Hazard Trees
 - E. Leaning Vegetation
 - F. Views into the Forest Obstructed by Vegetation
 - G. Invasion and Spread of Exotic Plants
 - H. Improper Drainage
 - I. Loss or Alteration of Native Plant cover
 - J. Utilities Screening

- IV. Ditch and Foreslope
 - A. Improper Drainage
 - B. Inadequate Sight Distance
 - C. Utilities Installation
 - D. Invasion and Spread of Exotic Plant Species
 - E. Loss or Alteration of Native Plant Cover
 - F. Damage to Roadway Structure
 - G. Damage to Cultural Structures
 - H. Wildfire Spread
- V. Road Shoulder
 - A. Damage to Roadway Structure
 - B. Safety Concerns
 - C. Invasion and Spread of Exotic Plant Cover
 - D. Loss or Alteration of Native Plant Cover
 - E. Damage to Cultural Structures
 - F. Wildfire Spread
- VI. Fillslope
 - A. Inadequate Sight Distance
 - B. Lack of Transition to Undisturbed Area
 - C. Unstable Fill Slope
 - D. Hazard Trees
 - E. Leaning Vegetation
 - F. Views into the Forest Obstructed by Vegetation
 - G. Invasion and Spread of Exotic Plants
 - H. Loss or Alteration of Native Plant Cover
 - I. Loss of Screening for Wildlife Habitat
- V. Transition

Appendix A: Roadside Inspection Sheet

Appendix B: Roadside and Maintenance Action Plan

Appendix C: References